

INDUSTRIAL APPLICATION OF RADIOISOTOPES



Edited by
G. Földiák



AKADÉMIAI KIADÓ, BUDAPEST

CONTENTS

1.	Basic data and definitions by <i>T. Lengyel</i>	13
1.1.	Symbols	13
1.2.	Basic definitions used in isotope techniques	14
1.3.	The major properties of the 100 most important radioisotopes	24
1.4.	Main properties of radioisotopes and isotopic preparations	32
1.4.1.	General properties of radioisotopes	32
1.4.2.	Main properties of sealed sources	44
1.4.2.1.	α -radiation sources	44
1.4.2.2.	β -radiation sources	45
1.4.2.3.	γ -radiation sources	46
1.4.2.4.	Neutron sources	47
1.4.2.5.	Special radiation sources	48
2.	Nuclear instruments and measurements by <i>S. Rózsa</i>	51
2.1.	Nuclear radiation detectors	51
2.1.1.	Gas ionization detectors	52
2.1.1.1.	Ionization chambers	54
2.1.1.2.	The proportional counter	56
2.1.1.3.	Geiger-Müller (GM)-counters	58
2.1.2.	Semiconductor detectors	62
2.1.3.	Scintillation detectors	67
2.2.	Basic types of radiation measuring and analysing instruments	75
2.2.1.	Counting rate meters	76
2.2.2.	Scalers	76
2.2.3.	Amplitude analysers	77
2.3.	Basic principles for industrial uses of nuclear measurements	80
2.3.1.	Radiation sources and containers	82
2.3.2.	Radiation detection in industrial environments	84
2.3.3.	Measuring systems for industrial problems	85
2.3.4.	Statistical measurement error	90
2.4.	Determination of physical material characteristics by nuclear measurements	91
2.4.1.	Level height determination	91
2.4.1.1.	Level height (extreme value) indication	92
2.4.1.2.	Continuous level height measurement	101
2.4.2.	Density measurement	107
2.4.3.	Quantity measurement	114
2.4.4.	Thickness measurement	117
2.4.5.	Coating thickness measurement	126
2.4.6.	Moisture content measurement	129
2.5.	Portable nuclear instruments	133
	References	136
3.	Radiotracer techniques by <i>G. Keömley</i>	138
3.1.	General considerations	138
3.1.1.	Preparation of the investigation	139
3.1.1.1.	Selection of the tracer isotope	139
3.1.1.2.	Preparation of the measurement, calculation of the necessary amount of isotope	144
3.2.	Identification of materials and detection of faults	153
3.2.1.	Identification of materials and tracking their movement	153

3.2.2. Detection of cracks and leaks	155	4.3
3.3. Determination of flow rates	159	4.3
3.3.1. Pulse-like tracer injection	160	4.3
3.3.2. Continuous tracer introduction	164	4.3
3.3.3. Examples of application	165	4.3
3.4. Study of material flow in industrial processes by <i>B. Balla</i>	167	4.3
3.4.1. Basic principles of unit operations	167	4.3
3.4.2. Determination of residence time distribution functions	171	4.3
3.4.3. Industrial examples of material flow studies	176	4.3
3.4.4. Study of the homogeneity of mixtures	179	4.3
3.5. Measurement of masses or volumes and mass transfer	181	4.3
3.5.1. Determination of masses or volumes	181	4.3
3.5.2. Wear studies	183	4.3
3.6. Tracer studies in physical and chemical research by <i>Z. Pádl</i>	189	4.3
3.6.1. Tracers in physical operations	189	4.3
3.6.1.1. Tracers in separation processes	190	4.3
3.6.1.2. Diffusion	191	4.3
3.6.1.3. Tracer studies in sorption and surface chemistry	192	4.3
3.6.2. Study of reaction mechanisms and kinetics	195	4.3
3.6.2.1. Isotopic exchange	195	4.3
3.6.2.2. The investigation of intermediates and reaction pathways	196	4.3
3.6.2.3. Reaction pathway studies by the determination of the position of the label	198	4.3
3.6.2.4. The kinetic isotope method	200	4.3
3.6.2.5. Double labelling	202	4.3
3.7. Radiotracers in studies of biologically active chemicals by <i>I. Elekes, L. Horváth and B. Pozsár</i>	205	5.
3.7.1. Pharmacokinetic and metabolic studies of drugs	205	5.
3.7.1.1. Pharmacokinetic studies	205	5.
3.7.1.2. Metabolic studies	212	5.
3.7.2. Radiotracer technique in pesticide research	214	5.
3.8. Radioisotopic age determination	217	5.
References	220	5.
 4. Radioanalytical methods by <i>[É. Bányai, T. Bálint, L. Gy. Nagy and E. Szabó]</i>	222	5.
4.1. Analytical methods based on physical interactions with radiation by <i>T. Bálint</i>	223	5.
4.1.1. Gas analysis based on ionization	223	5.
4.1.2. Analysis on the basis of β -absorption and scattering	227	5.
4.1.3. Analysis by absorption and scattering of X- and γ -rays	232	5.
4.1.4. Isotopic X-ray fluorescence analysis (IXRF)	239	5.
4.1.4.1. Theoretical basis	240	5.
4.1.4.2. Instruments	246	5.
4.1.4.3. Practical applications	250	5.
4.1.5. Analytical methods based on neutron absorption, scattering and moderation	259	5.
4.1.6. Analyses based on the Mössbauer effect	260	5.
4.2. Activation analysis by <i>L. Gy. Nagy and E. Szabó</i>	263	5.
4.2.1. Theoretical basis	263	5.
4.2.1.1. Neutron activation	263	5.
4.2.1.2. γ -activation	273	5.
4.2.1.3. Determination by means of charged particles	274	5.
4.2.2. Radiation sources used for activation analysis	275	5.
4.2.3. Measurement of radioactive samples	282	5.
4.2.3.1. Detectors	282	5.
4.2.3.2. Recording and evaluation of γ -spectra	283	5.
4.2.3.3. Chemical separations (destructive methods)	291	5.
4.2.4. Practical applications	293	5.
4.3. Analytical applications of tracer methods by <i>É. Bányai</i>	296	6.
4.3.1. Isotopic dilution	296	6.
4.3.1.1. Simple isotopic dilution	296	6.

4.3.1.2. Reverse and double isotopic dilution	298
4.3.1.3. Practical applications	299
4.3.2. Substoichiometric isotopic dilution	299
4.3.2.1. Solvent extraction of metal chelates	301
4.3.2.2. Other substoichiometric separations	308
4.3.3. Radioreagents	309
4.3.4. Radiometric titrations	312
4.3.4.1. Radioactive isotopes suitable as indicators	312
4.3.4.2. Extraction titrations	312
4.3.4.3. EDTA titrations	315
4.3.4.4. Precipitation titration	315
4.3.4.5. Redox and acid-base titrations	318
4.3.5. Radiochromatographic methods	318
4.3.5.1. Ion exchange radiochromatography	319
4.3.5.2. Extraction radiochromatography	321
4.3.5.3. Radio paper chromatography	321
4.3.5.4. Radio paper electrophoresis	323
4.3.5.5. Focussing paper electrophoresis	323
4.3.5.6. Radio thin-layer chromatography	324
4.3.5.7. Radio gas chromatography	325
4.3.6. Isotopic exchange reactions	327
References	329
 5. Nuclear borehole geophysics by I. Czeglédi	332
5.1. Natural γ -ray logging	333
5.1.1. Geochemical characteristics of rocks	335
5.1.2. Theory of the method	336
5.1.3. Interpretation of natural γ -ray logs	339
5.1.4. Application of the γ -ray method	343
5.1.5. Natural γ -spectroscopy	344
5.2. Methods using γ -radiation sources	345
5.2.1. γ - γ density logging	345
5.2.1.1. Procedure and interpretation	346
5.2.1.2. Application of the method	348
5.2.2. Selective γ - γ method	351
5.2.3. Other γ - γ methods	353
5.2.4. γ -neutron method	356
5.3. Methods using neutron sources	356
5.3.1. Methods based on isotope neutron sources	356
5.3.1.1. Conventional neutron methods	356
5.3.1.2. Neutron- γ spectroscopy	367
5.3.1.3. Neutron activation methods	367
5.3.2. Methods using neutron generators	369
5.3.2.1. Methods based on inelastic scattering of neutrons (fast neutron-neutron logging)	369
5.3.2.2. Activation using fast neutrons	371
5.3.2.3. Pulsed neutron-neutron method	372
5.3.2.4. Pulsed neutron- γ method	374
5.4. Tracer techniques in well logging	375
References	377
 6. Radiation technologies by G. Földiák	379
6.1. Radiation physical processes	383
6.1.1. Change of material structure	383
6.1.1.1. Electric conductors	383
6.1.1.2. Semiconductors	384
6.1.1.3. Insulators	385
6.1.2. Transformation of nuclear energy	386
6.1.2.1. Radioactive light sources	386

6.1.2.2. Radioactive electric power generators	387	7.3.1.
6.1.3. Changing the conductivity of the medium	389	7.3.2.
6.1.3.1. Elimination of electrostatic charges	389	7.3.2.1.
6.1.3.2. Ignition of electric discharges	392	7.3.2.2.
6.2. Radiation chemical processes	393	7.3.3.
6.2.1. Inorganic substances	393	7.3.3.1.
6.2.1.1. Gases	393	7.3.3.2.
6.2.1.2. Water and aqueous solutions	394	7.4.
6.2.1.3. Inorganic ion exchangers	396	7.4.1.
6.2.2. Organic substances	396	7.4.2.
6.2.2.1. Hydrocarbons	396	7.5.
6.2.2.2. Preparative processes	399	7.6.
6.2.2.3. Polymers	400	7.6.1.
6.3. Radiobiological processes	406	7.6.1.1.
6.3.1. Processes in agriculture and the food industry	407	7.6.1.2.
6.3.2. Sterilization of pharmaceuticals and medical instruments	410	7.6.1.3.
6.4. Radiation resistance of structural materials	413	7.6.2.
6.4.1. Inorganic materials	413	7.6.2.1.
6.4.1.1. Air	413	7.6.2.2.
6.4.1.2. Water and aqueous solutions	414	7.6.2.3.
6.4.2. Polymers	414	7.6.2.4.
6.4.2.1. Major technological consequences of radiation damages	414	7.6.3.
6.4.2.2. Factors influencing decomposition	416	7.6.4.
6.4.3. Various organic materials	418	7.6.4.1.
6.4.3.1. Lubricants and organic moderators	418	7.6.4.2.
6.4.3.2. Textiles	421	7.6.4.3.
6.4.3.3. Paints	421	7.6.4.4.
6.4.3.4. Adhesives	422	7.6.5.
6.4.3.5. Ion exchange resins	422	8.
6.4.4. Composite systems	424	8.1.
6.4.4.1. Cables	424	8.1.1.
6.4.4.2. Electronic parts	424	8.1.2.
6.5. The technology of irradiation	425	8.1.3.
6.5.1. Radiation sources	425	8.1.4.
6.5.2. Economic factors	428	8.1.4.1.
6.6. The control of irradiation	429	8.1.4.2.
6.6.1. Ferrous sulphate (<i>Fricke</i>) dosimetry	430	8.1.5.
6.6.2. Cerium sulphate dosimetry	433	8.2.
6.6.3. Chlorobenzene dosimetry	435	8.2.1.
6.6.4. Polymeric dosimeters	438	8.2.2.
6.6.5. Dose indicators (Monitors)	439	8.2.3.
References	439	8.2.3.1.
 7. Industrial radiography by <i>J. Hirling</i>	441	8.2.4.
7.1. Classification of radiographic methods	441	8.3.
7.1.1. Classification according to type of radiation	441	8.3.1.
7.1.2. Classification according to the energy of radiation sources	442	8.3.1.1.
7.1.3. Classification according to the detection of defects	443	8.3.1.2.
7.2. Techniques of gamma-radiography	445	8.3.2.
7.2.1. Laboratories for radiography	445	8.3.2.1.
7.2.2. Gamma-radiographic field-tests	450	8.3.2.2.
7.2.3. Preparation for radiography	453	8.3.2.3.
7.2.3.1. Selection of radiation source	453	8.3.3.
7.2.3.2. Planning the arrangement for radiography	453	8.3.3.1.
7.2.3.3. Determination of exposure time	456	8.3.3.2.
7.2.3.4. Complementary processes of radiography	459	8.3.3.3.
7.2.3.5. Processing and handling of film	460	8.4.
7.3. Radiographic sensitivity of images	461	8.4.1.

- 7.3.1. Measure of the radiographic sensitivity 461
7.3.2. Influence of image quality on radiographic sensitivity 467
7.3.2.1. Factors determining image contrast 467
7.3.2.2. Factors determining contour sharpness 468
7.3.3. Influence of film quality on radiographic sensitivity 470
7.3.3.1. Factors determining film contrast 470
7.3.3.2. Factors determining contour sharpness of the film 470
7.4. Evaluation of radiograms 471
7.4.1. Determination of welding defects 471
7.4.2. Classification and evaluation of casting defects 474
7.5. Neutron and proton radiography 475
7.6. Industrial autoradiography by *L. Barthá* 476
7.6.1. Efficiency of the autoradiographic method 477
7.6.1.1. Resolution power of autoradiography 477
7.6.1.2. Sensitivity of autoradiography 479
7.6.1.3. Error sources of autoradiography 479
7.6.2. Techniques of autoradiography 479
7.6.2.1. Sample preparation 480
7.6.2.2. Labelling the sample with radioactive isotopes 480
7.6.2.3. Choice of emulsion and its handling 480
7.6.2.4. Films for autoradiography 482
7.6.3. Quantitative autoradiography 482
7.6.4. Application of autoradiography 483
7.6.4.1. Investigation of diffusion processes 483
7.6.4.2. Investigation of segregation 485
7.6.5. Solid state track detectors in autoradiography 485
References 486
8. Radiation protection by *T. Biró* 488
8.1. General aspects of radiation protection 488
8.1.1. The role of radiation protection 488
8.1.2. Dose concepts 489
8.1.3. The Dose Limitation System 491
8.1.4. Calculation of dose rate 498
8.1.4.1. Dose rate in air 498
8.1.4.2. Shielding calculations 505
8.1.5. Measurement of dose and dose rate 511
8.2. Methods of prevention 512
8.2.1. Technical protection 513
8.2.2. Administrative and organizational measures 513
8.2.3. Packaging and transport of radioactive materials 514
8.2.3.1. Packaging 514
8.2.3.2. Transport 515
8.2.4. Handling of Wastes and Contaminated products, decontamination 516
8.3. Supervisory methods 516
8.3.1. Personal dosimetry 517
8.3.1.1. Personal dosimeters 517
8.3.1.2. Determination of incorporated radioactivity 519
8.3.2. Work place monitoring 520
8.3.2.1. Dose rate measurement 520
8.3.2.2. Surface contamination monitoring 520
8.3.2.3. Air monitoring 521
8.3.2.4. Industrial products and wastes 522
8.3.3. Records 523
8.4. Use of sealed sources 523
8.4.1. Definition of sealed source and leakage test 523
8.4.2. Containers for sealed sources 524
8.4.3. General aspects 525

8.4.3.1. Methods of protection	525	8.4.3.4. Service, maintenance	527
8.4.3.2. Preparatory measures	526	8.4.3.5. Incidents, accidents	527
8.4.3.3. Installation and control	526	8.4.4. Special duties	527
8.4.3.4. Service, maintenance	527	8.4.4.1. Industrial nuclear instruments	527
8.4.3.5. Incidents, accidents	527	8.4.4.2. Industrial radiography	528
8.4.4. Special duties	527	8.4.4.3. Radiation technologies	529
8.5. Application of unsealed radioactive substances	531		
8.5.1. General aspects	531	8.5.1.1. Methods of protection	531
8.5.1.2. Planning and design	531	8.5.1.3. Introduction of a tracer	532
8.5.1.4. Surveillance	533	8.5.1.5. Releasing materials, products	533
8.5.1.6. Incidents, accidents	534	8.5.2. Special duties	534
8.5.2. Tracer experiments	534	8.5.2.1. Tracer experiments	534
8.5.2. Radioanalytical work	534	References	535
References	535	Bibliography	535
Appendix by T. Lengyel	536		
Subject index	552		

Isoto
sym
isoto
prepT
radio
even
least
d'UrT
App
convN
app
diverU
edito
nota
sam
requ
symI
pla
notaT
meaA
A
a
c
D
E
h
I
 I_{rel}